

## Change Notice

## SW Series

# Deletion of Factory Code on SW3006A/U Case



Type of Change:

- Engineering
- Part Number
- Product
- Appearance



SW3006A/U Rocker

The SW Series rocker SW3006A/U will have a change to the printing on the case. Currently, the switch case has a UL marking and a factory code of 011. This will be revised to the same UL marking but without the numeric code. This change will effect both standard and custom models of SW3006A/U. The following table illustrates the differences before and after the revisions.

Before Change	After Change
 <p>Enlarged to Show Detail</p>	 <p>Enlarged to Show Detail</p>

### Notes

This change will effect only SW3006A/U in the SW Series Rockers.  
There will be no change to the country of origin (where switches are manufactured).  
Contact factory if more details are needed.

### Effective Date

Changes to SW3006A/U will be effective November 2015.

**NKK SWITCHES CO., LTD.** <http://www.nkk.com> E-mail: [nkkswitches@nkkswitches.co.jp](mailto:nkkswitches@nkkswitches.co.jp)

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031